



Please accept this proposal to perform the requested preventive maintenance items listed in the form "Preventative Maintenance Program Checklists," and change the combination as requested, on each vault asset or room number and to prepare and submit the required paperwork of each asset and the associated photographic documentation, As usual, the emergency escape cover key (Commonly, Medeco brand) need to present to access lock body for preventive maintenance routine and/or combination change.

CMI Cost Estimate								
Funding Request								
Multiple Sites								
Vault Combination								
CSS #18910 - CMI # 9505								
Prepared By: J. Bayne								
06.27.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
Preventive Maintenance								
Vault Combination								
1. Sites included								
1.1 MD006								\$200.00
1.2 PA003								\$200.00
1.3 PA011								\$200.00
1.4 PA013								\$200.00
1.5 PA017								\$200.00
1.6 PA050								\$200.00
1.7 PA052								\$200.00
1.8 PA053								\$200.00
1.9 PA079								\$200.00
1.10 PA079								\$200.00
1.11 PA087								\$200.00
1.12 PA096								\$200.00
Grand Total								\$2,400.00

If an asset is unavailable at the previously verified time, a return trip to complete the preventive maintenance and/or combination change is \$800.00 each asset



520 Edgewood Avenue Trafford, PA 15085-1121
(412) 380-3000 FAX: (412) 373-4100

PROPOSAL SUBMITTED TO

99th, ZONE B-5
STREET

DATE

6-26-2019

PHONE

CITY, STATE, ZIP CODE

JOB NAME

CSS# 18910

We hereby submit specifications and estimations for:

Please accept this proposal to perform the requested preventive maintenance items listed in the form "Preventative Maintenance Program Checklist," and change the combination as requested, on each vault asset or room number and to prepare and submit the required paperwork of each asset and the associated photographic documentation. As usual, the emergency escape cover key (Commonly, Medeco brand) need be present to access lock body for preventive maintenance routine and/or combination change.

Two-thousand four-hundred dollars (\$2,400.00) complete, for services on these assets:

MD006-00001	PA017-00001	PA079-00001 (1)
PA003-00001	PA050-00001	PA079-00001 (2)
PA011-00001	PA052-00001	PA087-00001
PA013-00001	PA053-00001	PA096-0000

If an asset is unavailable at the previously verified time, a return trip to complete the preventive maintenance and/or combination change is \$800.00 each asset.

Thank you for your consideration.

Craig A. Foocheck, CRL, CJS, GSAI:T
Owner/Operator
Craig@QualityLock.NET