



CUSTOMER QUOTATION NO. 287

CMI Management, Inc.
CMI Management, Inc.
Richard Hicks
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 12443
Quote No: 287
Site: MD021 Baltimore Road
Site Contact: Rick Hicks
Salesperson: Lindsay Ruby
Created Date: 06/23/2020
Valid For: 30 Day(s)

WO#: 12443

Problem: Chiller evaporator sensor is reading failed in the system.

S&S proposes to remove and replace the faulty evaporator sensor.
S&S will then complete a system check to ensure everything is running properly.

Service

Item	Quantity	Unit Price	Total
Evaporator Sensor/ 154174	1.00	\$75.30	\$75.30
Tax	1.00	\$16.87	\$16.87
Shipping	1.00	\$25.00	\$25.00
HVAC Labor Rate	8	\$100.00	\$800.00
Sub-Total ex Tax			\$917.17
Tax			\$0.00
Total inc Tax			\$917.17

Labor	\$800.00
Materials	\$117.17
Sub-Total ex Tax	\$917.17
Tax	\$0.00
Total inc Tax	\$917.17