



CUSTOMER QUOTATION NO. 297

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 12442
Quote No: 297
Site: DE007 Olgetown Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 07/01/2020
Valid For: 30 Day(s)

WO# 12442

CSS Ticket Number: 25176

Problem: Additional Repairs needed on Boiler. Adjustment screw requires replacement

S&S proposes to remove and replace the air plate adjustment screw on the boiler.
S&S will then complete a system check to ensure everything is running properly.

Service

Item	Quantity	Unit Price	Total
Air Plate Adjustment Screw/ 5-20-000601	1.00	\$25.20	\$25.20
External Star Washer	1.00	\$2.40	\$2.40
HVAC Labor Rate	10	\$100.00	\$1,000.00
		Sub-Total ex Tax	\$1,027.60
		Tax	\$0.00
		Total inc Tax	\$1,027.60

Labor	\$1,000.00
Materials	\$27.60
Sub-Total ex Tax	\$1,027.60
Tax	\$0.00
Total inc Tax	\$1,027.60