



**S&S MECHANICAL**

**S&S Mechanical**  
4831 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
www.sandsmidatlantic.com

## CUSTOMER QUOTATION NO. 649

CMI Management, Inc.  
5285 Shawnee Road Suite #510  
Alexandria VA 22312

**Quote Name:** 14166  
**Quote No:** 649  
**Site:** MD066 Fox Tail Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 06/28/2021  
**Valid For:** 30 Day(s)

**WO#: 14166**

**CSS Ticket Number: 30440**

**Problem:** HP 1-28 Room 211 - Serial Eprom Corrupted . HP 2-04 Room 200H -Condensate overflow alarm . HP 2-09 Room 211 - Alarm Red but running . HP 2-11 Room 204 North - Comp # 1 High Pressure alarm . HP 2-16 Room 207 Alarm Red but running . HP 2-20 Room 228 Comp #1 Low Pressure alarm . HP 2-35 Room 267 Comp #1 Low pressure alarm . HP 2-41 Room 225 Comp #1 High pressure alarm.

### 06/02/2021 - 06/15/2021 Work Note

All issues with this where resolved once new cards that were installed and addressed. System now controlling units affected by the bad cards. We are having a low pressure alarm on unit HP 2-15. Reset power and BMS system. System still low pressure Alarm. Need new low pressure switch and Board. Complete this job and new ticket needed for this unit.

S&S will reclaim refrigerant in unit HP 2-15.

S&S will remove and replace the the low pressure switch and control board on unit HP 2-15.

S&S will then fill system with refrigerant and complete a system check to ensure everything is running correctly.

### Service

Item	Quantity	Unit Price	Total
Low Press Switch /107225101	1.00	\$34.86	\$34.86
Control Board/ 668105801	1.00	\$475.56	\$475.56
Reclaim Tanks	1.00	\$158.40	\$158.40
Braising Material	1.00	\$125.00	\$125.00
Shipping	1.00	\$150.00	\$150.00
Diagnosis Fee	1	\$450.00	\$450.00
HVAC Labor Rate	9	\$100.00	\$900.00
<b>Sub-Total ex Tax</b>			\$2,293.82
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$2,293.82

<b>Labor</b>	\$1,350.00
<b>Materials</b>	\$943.82
<b>Sub-Total ex Tax</b>	\$2,293.82
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$2,293.82