

Date: 4/7/2025

Region: 4C

FEMS No.: 3071508

FAC ID: WV009

Maximo WO No.: 18459

Asset #: NA

Priority: Urgent



**Original Work Request:**

Repair entrance gate - won't close automatically after opening.

**Description of Repairs Needed:**

Labor and material to a) diagnose and repair, if possible, b) provide and replace (1) photo-eye, c) provide and replace (1) Hy-Security Smart Touch Motherboard, c) test for proper operation. If additional repairs are needed a separate quote will be provided.

**Labor:**

	Labor Hrs	Labor Rate	Total
2 Technicians (2 men x 16)	32	\$ 95.00	\$ 3,040.00
Administration	1	\$ 100.00	\$ 100.00

**Material List:**

	Quantity	Cost	Total
Photo-eye	1	\$ 626.89	\$ 626.89
Hy-Security Smart Touch Motherboard	1	\$ 1,044.00	\$ 1,044.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 3,140.00	\$ 1,670.89	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,810.89	\$577.31	\$288.65	\$5,676.85

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# Estimate

**ADDRESS**

Tidewater Inc.  
 6625- A Selnick Drive  
 Elkridge, MD 21075

**ESTIMATE #** 2672**DATE** 03/27/2025**P.O. NUMBER**

Clarksburg, WV D&R Ent. Gate

	ACTIVITY	QTY	AMOUNT
03/27/2025	<b>Services</b> Clarksburg, WV USARC Diagnose & Repair Entrance Gate (FEMS #3071508)	1	4,810.89

Dear Ms. Pape,

As per your request, LoCurrent Systems is pleased to provide a quotation to Diagnose and Repair if possible the issues being experienced with the Entrance Gate as per the following description "Repair entrance gate - won't close automatically after opening." This quotation is based on service being provided while in the region attending to additional service calls. As of April 2, a power surge occurred at the facility which has been reported for revision of this Estimate per the following description "gate control board fried, not engaging."

#### Cost Breakdown:

(1) Photoeye.....\$626.89  
 (1) Hy-Security Smart Touch  
 Motherboard....\$1,044.00  
 (2) men 16 hrs @  
 \$95/hr.....\$3,040.00

ACTIVITY	QTY	AMOUNT
Administration.....	\$100.00	
Grand Total.....	\$4,810.89	
The cost for the above mentioned work is \$4,810.89.		
If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.		
Thank you for thinking of LoCurrent Systems.		
Sincerely,		
Antonietta LoRusso		

TOTAL **\$4,810.89**

Accepted By

Accepted Date