



CUSTOMER QUOTATION NO. 485

CMI Management, Inc.
CMI Management, Inc.
Richard Hicks
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 13464
Quote No: 485
Site: MD021 Baltimore Road
Site Contact: Rick Hicks
Salesperson: Liz Richardson
Created Date: 01/18/2021
Valid For: 30 Day(s)

WO# 13464

CSS# 28446

Problem: NR Repair Mixer (HOBART) Electrical Issues

S&S proposes to remove and replace the timer knob/board on the Hobart mixer.

S&S will then complete a system check to make sure everything is running as intended.

Service

Item	Quantity	Unit Price	Total
Potentiometer Assembly	1.00	\$83.36	\$83.36
Shipping	1.00	\$17.53	\$17.53
Diagnosis Fee	3	\$100.00	\$300.00
Hot Side Labor Rate	4	\$100.00	\$400.00
		Sub-Total ex Tax	\$800.89
		Tax	\$0.00
		Total inc Tax	\$800.89

Labor	\$700.00
Materials	\$100.89
Sub-Total ex Tax	\$800.89
Tax	\$0.00
Total inc Tax	\$800.89