

Additional Funding Request

Submitted: 3/14/2019

DE001 – water analysis DE002 – water analysis DE007 – water analysis MD002 – water analysis MD003 – water analysis MD019 – water analysis	CSS #18208 WO#8253
Description of Repairs	Initial water analysis, documentation and recommendation for closed loop water systems performed by Bond Water Technologies.
Original SC Investigative Diagnosis	\$900.00 \$150 for each site visit at DE001, DE002, DE007, MD002, MD003, MD019 Zone 2, Region 5
Diagnosis: Initial Work Order	Site visits for boiler corrosion inhibitor costs.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	Materials: = NA
Additional Labor Cost to Perform Repairs	Labor: NA
Total Cost of Repair	\$900.00