



Facility Repair Proposal

Region: 4C
Fac ID: WV006
Date: 2/6/23

CSS # 91504
Maximo Work Order No.: 11801

Asset ID: NA

Original Work Request:

Front entrance gate CAC reader has power, but not reading the CAC cards.

Description of Repairs Needed:

Labor (approximately 16 hours) and material to a.) repair/replace the Front Gate Entrance CAC Reader.

Parts List:

CAC Reader

Equipment List: NA

PM History:
NA

Cost Proposal:

See attached RS Means Estimate.

Total Cost: \$3253.01

Estimate Name: CSS 91504 - WO 11801 - WV006 Repair-Replace Front Gate Reader

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 101 Lakeview Drive, Cross Lanes, WV 25313-1485
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2023	
						Labor Type: Repair & Remodeling	
						City Cost Index: WEST VIRGINIA / CHARLESTON (250-253)	