



Date: 3/14/2023

Region: 4C
FAC ID: WV007

CSS No.: 91651
Maximo Work Order No.: 12294

Asset #: NA

Original Work Request:

No heat call for 2nd Floor offices 212, 213 and 215 possibly AHU 5 mixing valve issue.

Description of Repairs Needed:

Labor to troubleshoot, diagnose and make necessary repairs and adjustments to the 2nd floor offices 212, 213 and 215. a.) Reset the AHU's 6, 7 and 8. b.) Remove the overrides on the boilers and hot water pumps. c.) Reset AHU #4 and the motor controls that was tripped on the freeze sensor.

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$728.64	\$0.00	\$728.64