



Date: 4/7/2023

Region: 4C
FAC ID: WV007

CSS No.: 91916
Maximo Work Order No.: 12106

Asset #: NA

Original Work Request:

Replace Motor in Bathroom Exhaust Fan

Description of Repairs Needed:

Labor and material to a.) Exhaust Fan Motor (Dayton- Model 4YU27, 115v)

Material List:

(1) Exhaust Fan Motor (Dayton- Model 4YU27, 115v)

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$899.62	\$837.31	\$1,736.93