



Date: 3/27/2023

Region: 4C
FAC ID: WV014

CSS No.: 92029
Maximo Work Order No.: 12089

Asset #: NA

Original Work Request:

Repair outdoor IDS speaker and existing wiring. Replace outdoor siren in front of building.

Description of Repairs Needed:

Labor and material to a.) to diagnose repair/replace (2) exterior IDS Vault Sirens at the Grafton, WV USARC. Please note: Contractor shall utilize existing Wiring.

Material List:

(2) IDS Sirens

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
16	\$2,008.64	\$466.82	\$2,475.46