



Date: 3/22/2023

Region: 4A
FAC ID: NY010

CSS No.: 92680
Maximo Work Order No.: 12506

Asset #: NA

Original Work Request:

Repair the HVAC controls by updating existing controls to latest version of Niagara controls

Description of Repairs Needed:

Labor to a.) update existing controls to latest version of Niagara and install breaker lockout on
drill hall temperature control panel breaker

Material List:

Breaker lockout

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
15	\$2,061.33	\$41.75	\$2,103.08