



Date: 4/25/2023

Region: 4C
FAC ID: WV029

CSS No.: 92869
Maximo Work Order No.: 12557

Asset #: 3160

Original Work Request:

Repair actuator AHU#1 - needs replaced before cooling season starts

Description of Repairs Needed:

Labor and material to a.) replace the LF24SR belimo damper actuator SR 24V 35in-lb 2-10VDC

Material List:

(1) LF24SR belimo damper actuator SR 24V 35in-lb 2-10VDC

Equipment List:

NA

PM WO History:

11843

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
5	\$658.54	\$456.66	\$1,115.20