



Work Order  
No: 60597

Armistead Mechanical Inc. Services  
168 Hopper Avenue, Waldwick NJ 07463

Date: 8/31/2022

Status: Schedule

<b>Service To:</b> SSG Frederick J III Jr USARC <b>Address:</b> 2500 NY Route 17K Bullville NY 10915	<b>Contact:</b> <b>Phone:</b>
--	----------------------------------

#### Work Summary

Air Conditioner not working in ARC AHU-1 shows "alarm 2021

#### Equipment

ID	Description	Type	Make	Model	Serial Number	Location	Year Installed

#### Labor

Date	Technician	Hours
8/31/2022	20061 (Michael T. LaMagna)	3.00

#### Parts

Description	Quantity

#### Notes

Topic	Note
WORK ORDER NOTES	8/31/22 ML - Arrived on site. Checked in with Sargent. Gained access to unit and identified alarm 2021 on VFD. Contacted ABB and went through diagnostic procedures to determine the drive had a defective control board. ACH 550 is being phased out according to manufacturer and superseded mode is ACH580, which they recommend upgrading to. Left unit off to prevent any further damage to equipment and system is not operational. Forwarded info to supervisor to quote repairs

Customer Signature		Signed By		Date	
--------------------	--	-----------	--	------	--