



Work Order
No: 63345

Armistead Mechanical Inc. Services
168 Hopper Avenue, Waldwick NJ 07463

Date: 6/28/2023
Status: Schedule

Service To: SSG Frederick J III Jr USARC Address: 2500 NY Route 17K Bullville NY 10915	Contact: Phone:
--	----------------------------------

Work Summary

AMSA radiant pump leak

Equipment

ID	Description	Type	Make	Model	Serial Number	Location	Year Installed

Labor

Date	Technician	Hours
5/23/2023	20014 (David J. Hinnrichs)	2.00
6/28/2023	20014 (David J. Hinnrichs)	6.00

Parts

Description	Quantity

Notes

Topic	Note
WORK ORDER NOTES	5/23 DH. Isolate pump. Drain glycol, put into glycol tank. Isolate and remove electric. Remove pump for repair. Impeller looks rough, may require new at additional cost. Will verify. 6/28 DH. Picked up pump. Installed, purged, wired and tested. Check rotation.

Customer Signature		Signed By		Date	
---------------------------	--	------------------	--	-------------	--