

Additional Funding Request

NY127	CSS# 93779 WO# 22721							
Description of Repairs	Labor and material to a.) clean the condenser coils on 2 Liebert mini mate air conditioning systems and check refrigerant charges							
Diagnosis: Initial Work Order	OMS TR room AC not working. Computer room a/c not working room alarm going off indicating high temperature							
Diagnostic Fee	NA							
Additional Labor Cost to Perform Repairs	4 Hours x \$128.00 = \$512.00							
Additional Material Cost to Perform Repairs	<table><tr><td>Misc materials (See attached detail)</td><td>NA</td><td>\$50.00</td><td>\$50.00</td></tr></table>				Misc materials (See attached detail)	NA	\$50.00	\$50.00
Misc materials (See attached detail)	NA	\$50.00	\$50.00					
Total Cost of Repair	\$ 562.00							

MUA COST DATA ANALYSIS AND NEGOTIATION. THE LABOR HOURS IS WITHIN THE LOCAL SCA WAGE RATE FOR THE WORK DURATION PROPOSED WHICH IS TO CLEAN THE CONDENSER COILS ON 2 LIEBERT AC SYSTEMS AND CHECK REFRIDGERANT LEVELS. THE MEANS AND METHODS PROPOSED FOR THIS REPAIR WORK IS TYPICAL OF WORK COMPLETED AT OTHER NY FACILITIES AND CONSIDERED FAIR AND REASONABLE.



June 12, 2023

Tidewater
US Army Corps of Engineers
881 Stanton Rd
Nichols, NY 13812

Attn: Karlee Demain

Re: clean condenser coils and check refrigerant charge

Ms. Demain,

Postler & Jaeckle Service is pleased to provide a quote to clean the condenser coils on 2 Liebert mini mate air conditioning systems and check refrigerant charges. Your cost for this service will be \$512.00 for labor and \$50.00 materials for a total of \$562.00. This quote is based on work being performed during normal working hours of 8:00am to 4:30pm Monday through Friday. Thank you for the opportunity to provide this quote for your facility. Please contact me with any questions.

Sincerely,

DAVE HENDEE

Field Sales Support

Postler & Jaeckle Corp.

2000 Lake Rd., Elmira, NY 14903

T 607-739-8303 | C 607-215-6523

E: dhendee@postler.com