

## SERVICE REPORT

DATE 2024 7 2 ARRIVAL TIME 6:30 DEPARTURE TIME 3:00 JOB/TCK. NO. 210204

CUSTOMER P.O. NO. CSS# 98269

**JOB NAME/LOCATION** *USARC - New River Valley Memorial VA012*

**SERVICE REQUESTED** *Pot feeder that was previously installed (by others) was not properly set up, it only has a high pressure line and no low*

Manufacture: <u>Other</u>				
Model#: <u>SOLO 399</u>				
Serial#: <u>PS69278</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

Arrived and found one boiler in pieces and other running. looked at pot feeder and found were it was not plumbed correct and found how it needed to be piped up. Made a parts list and will quote.

### NATURE OF WORK

Regular Service \_\_\_\_\_  
Quoted Service \_\_\_\_\_  
Start-up/Warranty \_\_\_\_\_  
SPD \_\_\_\_\_  
Contract Service \_\_\_\_\_  
Energy Management \_\_\_\_\_

### PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

## SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_  
Customer Representative