

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 11-8-23 ARRIVAL TIME DEPARTURE TIME JOB/TCK NO 200630

CUSTOMER PO. NO. CSS93892

JOB NAME/LOCATION *USARC - South Ridge*

SERVICE REQUESTED (10) Investment is to replace 2-inch Copper 90 and piping on the CW Supply.

| | | | |
|----------------------|-----|----|----|
| Manufacture: | | | |
| Model#: | | | |
| Serial#: | | | |
| Refrigerant Added: | Qty | lb | oz |
| Refrigerant Removed: | Qty | lb | oz |

- Leak Tested
- Leak Found
- Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

WORK PERFORMED/JOINT INFO:
Picked up materials and equipment from the warehouse and the supply house. Arrived on site, checked in with customer. This repair has to be made with the cold water supply turned off and they were already people onsite and it was not communicated for the building to be empty. We tried to work something out to clear the building but are not able to. We rescheduled for next Monday so the people can properly be notified to not come in. Unloaded the materials and equipment at the job site for when I return.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES _____ NO X EXPLAIN _____

SIGNATURE _____

Customer Representative