



Invoice

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd
Alexandria, VA. 22312

Jun 3, 2022

RE: Door threshold NY060
W/O 17185
CSS# 35503

- Service Call
- Remove double door threshold.
- Remove broken and heaved concrete beneath sill.
- Apply Ardex concrete leveler over existing concrete to level.
- Install aluminum threshold to match existing.

(1) Aluminum 6 ft threshold Grainger #45AA08.	195.83
1 Ardex leveler.	32.82
Labor 6 x 120.00	720.00

	948.65
20% profit/OH.	189.73

Total Cost \$1138.38