

Additional Funding Request

Submitted: 11/20/2020

VA011	CSS #27506 WO#13158								
Description of Repairs	Upon inspection found unit out on Low Pressure.								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	Moore's will recover refrigerant, pressurize system and check for leaks, and make necessary repairs. (This quote covers minor brazing, no replacement of parts.)								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$345.00</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Materials (See detail on Moore's proposal)</td> <td style="padding: 2px;"></td> <td style="padding: 2px;"></td> <td style="padding: 2px;">\$345.00</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Materials (See detail on Moore's proposal)			\$345.00
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Materials (See detail on Moore's proposal)			\$345.00						
Additional Labor Cost to Perform Repairs	<p>Labor: \$1,380.00 (see detail on labor on Moore's proposal)</p>								
Total Cost of Repair	\$1,725.00								