

Date:

Region:   
FAC ID:

CSS No.:   
Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

IDS System went offline with a power outage and at first it came back up and then McCoy called and it went down and they were not able to see the Galaxy Vault. It is suspected that the mother board is affected. Recommended contractor: LoCurrent

**Description of Repairs Needed:**

Proposal is to diagnose and repair if possible the issues being experienced with the Galaxy, VA Vault IDS as per the description of issues provided.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	24	\$ 95.00	\$ 2,280.00
Administrative	1	\$ 100.00	\$ 100.00

**Material List:**

	Quantity	Cost	Total
DSC Powerseries TL260	1	\$ 200.92	\$ 200.92
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$2,380.00	\$200.92	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,580.92	\$309.71	\$154.86	\$3,045.49