

Additional Funding Request

VA048	CSS# 27758 WO# 13308 Asset# NA							
Description of Repairs	Monteith Facility VA048 AMSA Building Aiphone Intercom Repair while on site performing estimate #1691. Diagnosed that the Monteith Facility VA048 AMSA Building Aiphone Intercom needs to be replaced.							
Diagnosis: Initial Work Order	Keypad at AMSA gate is not functioning properly. The key pad is not a CAC system, it's a numerically pin code button device							
Diagnostic Fee	\$ 450							
Additional Labor Cost to Perform Repairs	\$1,250 Labor 2 men \$75 /hr x 8 Administrative Fee \$50.00							
Additional Material Cost to Perform Repairs	\$205 <table border="1"><tr><td>AiPhone LEM-1 DLS</td><td>1</td><td>205</td><td>205</td></tr></table>				AiPhone LEM-1 DLS	1	205	205
AiPhone LEM-1 DLS	1	205	205					
Total Cost of Repair	\$ 1,905							

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1702

DATE 12/08/2020

P.O. NUMBER

Monteith VA048 AMSA AiPhone Int

	ACTIVITY	QTY		AMOUNT
12/08/2020	Services Follow Up Quotation as per Invoice #1801 (CSS#27758; WO#13308): Monteith Facility VA048 AMSA Building AiPhone Intercom Repair While on site performing Estimate #1691, diagnosed that the Monteith Facility VA048 AMSA Building AiPhone Intercom needs to be replaced. Cost Breakdown: (1) AiPhone LEM- 1DLS.....\$205.00 (2) men 8 hrs @ \$75.....\$1,200.00 Administrative.....\$50.00 Grand Total.....\$1,455.00 The cost for the above mentioned work is \$1,455.00. If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed. Thank you for thinking of LoCurrent Systems. Sincerely, Antonietta LoRusso	1	1,455.00	1,455.00

TOTAL	\$1,455.00
-------	------------

Accepted By

Accepted Date

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

INVOICE # 1801
DATE 12/04/2020
DUE DATE 01/03/2021
TERMS Net 30

P.O. NUMBER

Montieth AMSA Diagnose Intercom

ACTIVITY	QTY	RATE	AMOUNT
Services As per Estimate #1691: Montieth Facility Richmond VA048 CSS# 27758 WO# 13308 Repair/Replace nonfunctional Keypad AiPhone Intercom Diagnostic- Arrived on site to find that Keypad is 100% operational. While on site found issue to be AiPhone Intercom. Diagnosed and found that Intercom is beyond repair and needs to be replaced with new. Will be sending a follow up quotation to supply and install new AiPhone Equipment to replace nonfunctional to achieve proper operation.	1	450.00	450.00

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.

BALANCE DUE

\$450.00



AIPHONE
LEF-3

VOICE VOL.





AIPHONE
CALL

1

2

3

4

5

6

7

8

9

*

0

#

Linear