

Additional Funding Request

VA049 HVAC Mold concerns	CSS #20813 WO# 10598
Description of Repairs	<ul style="list-style-type: none"> - Investigate Mold growth and check HVAC system for proper operation.
Diagnosis: Initial Work Order CSS# 20813	<ul style="list-style-type: none"> - Investigate Mold growth and check HVAC system for proper operation.
Original SC diagnosis = \$150.00	<ul style="list-style-type: none"> - \$1080.00 1 HVAC tech/ 9 hours/ \$120 an hour
Explanation of Additional Costs for Repairs	<ul style="list-style-type: none"> - Investigate Mold growth and check HVAC system for proper operation. -SEE ATTACHED Service report -
Additional Labor Cost to Perform Repairs	Labor = \$1080 to return IF need to further diagnosis -pending talks between Moore's and facility manager -
Additional Material Cost to Perform Repairs	<ul style="list-style-type: none"> - N/A
Total Cost	Total = \$2160