

## VA050 Chiller #2 Update -New CSS ticket needed -Additional repairs are needed

Richard Hicks <richard.hicks@cmimgmt.com>

Fri 7/16/2021 4:59 PM

To: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil>; Williams-Taylor, Angela W CTR USARMY 99 RD (USA) <angela.w.williams-taylor.ctr@mail.mil>; Adam Colopy <adam.colopy@tideh2o.net>; Gabrielle Mascelli <gabrielle.mascelli@tideh2o.net>; Mary Lowery <Mary.Lowery@tideh2o.net>  
Cc: William Schultz <william.schultz@tideh2o.net>

Scott , Team,

Good news -I just spoke to Moore's , the #2 chiller is operating at 75% .-This scope of work under WO# 14526 CSS# 30717 has been completed

| Work Order | Description                                         | Site   | Location / Fac. ID | CSS # | Zone | STK Qty | Priority | Status  | Work Type |
|------------|-----------------------------------------------------|--------|--------------------|-------|------|---------|----------|---------|-----------|
| 14526      | Chiller Trouble shooting needed -Additional efforts | 99REG5 | VA050-01           | 30717 | Z3   | 11      | 3        | INPRG-C | STK       |

On Monday, please give me a NEW CSS Ticket -for -VA050 -#2 Chiller Leak check circuit #2 -it's low on freon and circuit #2 expansion valve and liquid solenoid valve are hanging up and need to be replaced .

Thanks,  
Rick

Have a Good weekend !

Rick Hicks  
PM / 99TH -Region 5  
5285 Shawnee Road  
Suite #510  
Alexandria , VA 22312  
703-738-5301  
Richard.Hicks@cmimgmt.com