

Tina Lee

From: William Schultz <william.schultz@tideh2o.net>
Sent: Wednesday, May 11, 2022 4:22 PM
To: Adam Colopy; Richard Hicks; Tina Lee; Mary Lowery
Subject: [EXTERNAL]VVA050 Chiller

CAUTION: This email has been received from outside of CMI - Use caution before clicking on links, opening attachments, or responding.

CHiller 1 has to contactors that need to be replaced. Also found fuse blown do to a condenser fan motor bad and single phasing the fuse. Earl from Moores will swing by Friday and replace fuse so he can determine which fan motor is bad. Chiller 2 has 2 bad contactors as well as supply and return chilled water sensors that are bad. Earl from Moores will work up a quote to repair all the deficiencies.

Both Chillers are working right now but repairs will need to be addressed before the hot days of summer arrive.

Sent from my T-Mobile 5G Device

Get [Outlook for Android](#)