

Additional Funding Request

Site: VA050	WO# 3445, 3446 CSS # 15881 Asset# NA
Description of Repairs	Diagnose issues with hot water pump bearings
Diagnosis: Initial Work Order CSS# 15581	Diagnose issues with hot water pump bearings
Explanation of Additional Costs for Repairs	Labor to diagnose problems with hot water pump bearings
Additional Labor Cost to Perform Repairs	\$ 4x120.00- 480
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$ 480-\$250 PM credit= \$230.00



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

October 30, 2018

Quotes are valid for 30 days.

ISG USARC VA050	Contact Name	George Grant
	Telephone	
	Cell Phone	304.663.8670
Email	Fax Number	
		ggrant@internationalsupportgroup.com

DESCRIPTION OF EQUIPMENT:

DESCRIPTION OF PROBLEM:

**Diagnose hot water pump
bearings**

DESCRIPTION OF REPAIRS:

MATERIAL, EQUIP OR PARTS

Quantity Sell price

\$
\$
\$
\$

Material Total

\$

LABOR ITEMIZED

Labor - One Man
Labor - Second Man

4
0

		Labor
\$	120.00	\$ 480.00
\$	120.00	\$ -
Labor Total		\$ 480.00

Thank you for your business. If you have any questions or concerns,
please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$
Labor	\$ 480.00
TOTAL	\$ 480.00

*This does not include
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591
Amy Hockaday, Estimator 434-309-2569
James Davis, Estimator 434-309-2568
Adam Barker, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.