

REVIEWED

By Mike Merchan at 1:14 pm, Feb 27, 2019

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
PHOTOCELL

SITE AND BLDG #: VA099-01

LOCATION/RM #: POV

MECHANIC
SIGNATURE: *Turk*

DATE: 2/27/19

START TIME: 9 AM

FINISH TIME: 11 AM

| Site Location | WO # | Asset # | PM # | Manufacturer | Model Number | Serial # | Asset Description | Asset Location |
|---------------|------|---------|------|--------------|--------------|----------|---|----------------|
| VA099-01 | 7250 | 1613 | | VALMONS | BG790-50- 11 | | J-1502000-43 14-pc Photocell POV Lights | |

| CHECK POINT | CHECKPOINT DESCRIPTION | TASK COMPLETE | | NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION) |
|---|---|---------------|----|---|
| | | YES | NO | |
| SPECIAL INSTRUCTIONS | | | | |
| 1 | In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered. | | | |
| 2 | Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work. | | | |
| TO BE PERFORMED AT EACH INSPECTION SERVICE | | | | |
| 1 | Ensure the is operating properly and is free of abstractions and/or damage. | | | |
| 2 | Damaged should be repaired as necessary to maintain their effectiveness. | | | |
| 3 | Clean and/or remove debris/sediment accumulation as necessary. | | | |

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

