

**PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST**  
**PHOTOCELL**

SITE AND BLDG #: VA099-02

MECHANIC  
SIGNATURE: *Tn C*DATE: *2/27/19*

LOCATION/RM #:

START TIME: *9 AM*FINISH TIME: *10 AM*

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
VA099-02	7251	1616			ED079480T12 EFD		J-1502000-43 20-pc Photocell	Motor Pool Lights

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
<b>SPECIAL INSTRUCTIONS</b>				
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered.			
2	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.			
<b>TO BE PERFORMED AT EACH INSPECTION SERVICE</b>				
1	Ensure the is operating properly and is free of abstractions and/or damage.			
2	Damaged should be repaired as necessary to maintain their effectiveness.			
3	Clean and/or remove debris/sediment accumulation as necessary.			

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

MOORES WAS ON SITE and will submit quote  
Electric

for insperable lights above supply rooms.