

Additional Funding Request

Site: VA099	WO# 10128 CSS # 18471 Asset# NA
Description of Repairs	Replace glycol makeup package
Diagnosis: Initial Work Order CSS# 18471	Replace glycol tank
Explanation of Additional Costs for Repairs	Labor and material to replace glycol makeup package
Additional Labor Cost to Perform Repairs	6 x \$80.00 = \$480.00
Additional Material Cost to Perform Repairs	\$1,562.40
Total Cost of Repair	\$2,042.40

WORK ORDER ESTIMATE

CSS #: 18471

Work Order #: 10128

Emergency ☐

Urgent ☐

Routine ☒

Company Name:	ISG	Facility ID:	VA099
Contractor POC:	Jamie Merchant		
Telephone No:	936-689-9020	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	jmerchant@internationsupportgr		
Assigned Technician(s):	John Suthard		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Replace Glycol Tank

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Glycol Tank		\$1,302.00		\$0.00
				\$0.00
				\$0.00
SUB-TOTAL COSTS:		Materials Total	Labor	\$480.00
TOTAL			\$2,042.40	



Controller

[Home](#) > [Glycol Feeders](#) >

Propylene Glycol Feeder

LARGER PHOTO **EMAIL A FRIEND**

Glycol Feeder - 30 to 150 Gallon Tanks

Propylene Glycol Feeder

Our Price: \$1,302.00**Sale Price: \$1,202.00**

Savings: \$100.00

UPDATE PRICE

Quantity in Stock:6

Availability: Usually Ships in 2 to 4 Weeks

Product Code: CW-GF

The following document(s) will be emailed upon shipment of your order or download now:

- 1 - Glycol Feeder Data Sheet pdf file (\$0.00)

CHOOSE YOUR OPTIONS:

Tank Selection:

4.8 ★★★★★

Google
Customer Reviews