

**CERTIFICATION OF WORK  
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039 Date of Visit: 3/10/21, 3/15/21

Contractor Personnel on Site:

1. Patrick Brown 3. \_\_\_\_\_  
2. \_\_\_\_\_ 4. \_\_\_\_\_

**Work Performed:**

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO#'S, 11920, 11999, 12000, 12031, 12032, 12206,
2. 12214, 12221, 12233, 12233, 12066
3. ASSET#'S, 190917-248, 9891, 9896, 9932, 9935, 9891,
4. 190917-269, 264, 248, 249, 9943
5. \_\_\_\_\_

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Patrick Brown Date: 3/15/21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SSGT JAMES KELLEY Date: 3/15/21

Signed: 

E-Mail: \_\_\_\_\_

**PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST**  
**DUCTLESS MINI SPLIT**

SITE AND BLDG #: **NY039 BLDG1**MECHANIC  
SIGNATURE:DATE: **3/10/21**LOCATION/RM #: **RM1115** WO# **11920**ASSET # **190917-248**START TIME: **8am**FINISH TIME: **8:30am****12233**

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
<b>SPECIAL INSTRUCTIONS</b>				
1	As needed, de-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work. Follow lock out/tag out procedures at all times.	✓		
<b>TO BE PERFORMED AT E/CH INSPECTION SERVICE</b>				
1	Check fan blades for dust buildup and clean if necessary.	✓		fan blades are clean
2	Check all electrical connections	✓		electrical connections are good
3	Check that the fan runs properly in all speeds as applicable.	✓		fan functions properly in all speeds
4	Check dampers and rotating auto diffusers for dirt accumulations, clean as necessary.	✓		all are clean
5	Check filter door for proper gasketing and air leaks. Correct as needed.	✓		No air leaks
6	Change or Clean filter as needed. Filters get checked quarterly.	✓		filters are good
7	Ensure condensate pump is working properly and that the drain lines are clear.	✓		drain lines are clear
8	Clean up work area.	✓		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

**Additional Notes:**