

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA011 Date of Visit: 7/6/2020

Contractor Personnel on Site:

- | | |
|--------------------------|----------|
| 1. <u>RICHARD WALKER</u> | 3. _____ |
| 2. _____ | 4. _____ |

Work Performed:


Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO's 12363 AN, 12412SA, 12426 PMM, 12440PMS
2. _____
3. _____
4. _____
5. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Richard Walker Date: 7/6/2020

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Chris Chippa Date: 7/6/2020

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

FENCES

SITE AND BLDG #: VA011-01

MECHANIC

SIGNATURE: *[Signature]*

DATE: 7.6.2020

LOCATION/RM #: *outside* Mech Room WO# 12363 ASSET # 1381

START TIME: 9am

FINISH TIME: 5pm

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check posts and corner posts, support guys, and horizontal bars between each support post.	<input checked="" type="checkbox"/>		
2	Check wire and anchor point; re-stretch and re-anchor if necessary.	<input checked="" type="checkbox"/>		
3	Inspect fence anchors along the bottom of the fence and at the point where the fence is connected to the post.	<input checked="" type="checkbox"/>		
4	Report any damage to fence that would cause a security concern	<input checked="" type="checkbox"/>		
5	Inspect the bottom of the fence to ensure that there is not a gap larger than 2 inches under the fence.	<input checked="" type="checkbox"/>		
6	Check the top guard and ensure that it is properly fastened (angled out) and the wires are tight.	<input checked="" type="checkbox"/>		
7	Inspect all wire ties. Note any deficiencies	<input checked="" type="checkbox"/>		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: