

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE007 Date of Visit: 9/24/20

Contractor Personnel on Site:

- | | |
|----------------------|----------|
| 1. <u>JOHN BROWN</u> | 3. _____ |
| 2. _____ | 4. _____ |

Work Performed:


Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO'S 12643MO,12668QT,12694SA,12730PMQ,12737PMS,12644MO
2. LIGHTING, CIRCULATING PUMPS, HVAC CONTROL PANELS,
3. EXPANSION TANKS, GLYCOL FEEDER, WALL PACKS, GATE
4. _____
5. _____

CERTIFICATION OF WORK


To be signed by the Contractor:

Print Name: Johnny W Brown Date: 9/24/20

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank:  Danielle Barrett Date: 9/24/20

Signed: _____

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

LIGHTING, OUTSIDE

SITE AND BLDG #: **DE007-01**MECHANIC
SIGNATURE: DATE: **9/24/20**LOCATION/RM #: **WO# 12643 ASSET # 1453**
12694 1771START TIME: **0900**FINISH TIME: **1630**

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
SPECIAL INSTRUCTIONS				
1	Schedule and coordinate work with operating personnel.	☒	☐	
2	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	☒	☐	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Inspect lighting contactor for pitting or arcing - report issues	☒	☐	
2	Inspect visual condition of wiring. Look for evidence of overheating.	☒	☐	
3	Check for proper light operation.	☒	☐	
4	Test operation of automatic switches/ time clock/ photocells if applicable.	☒	☐	
5	Inspect light pole and mounting devices for deficiencies.	☒	☐	
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.	☒	☐	I found a few lights out

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

