

**CERTIFICATION OF WORK  
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY067 Date of Visit: 6/22/21

Contractor Personnel on Site:

- |                         |          |
|-------------------------|----------|
| 1. <u>PATRICK BROWN</u> | 3. _____ |
| 2. _____                | 4. _____ |

**Work Performed:**

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO#'S, 12884, 12918-12921, 12976-12980, 13044, 13073,
  2. 13074, 13148-13153, 13274, 13284, 13315, 13075,
  3. 13154-13157, 13316, 13317
  4. ASSET#'S, 10552-10558, 10547-10550, 10610, 10615, 10612,
  5. 10611, 10617-10619, 10641, 10623-10625, 10642, 190917-, 423,  
424, 427, 428, 451, 450, 423-428, 429, 448, 460, 462,
- 

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Patrick Brown Date: 6/22/21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: MICHAEL MAROTTA Date: 6/22/21

Signed: 

E-Mail: \_\_\_\_\_

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### UNIT HEATER, HOT WATER

SITE AND BLDG #: NY067 BLDG2

MECHANIC  
SIGNATURE: 

DATE: 6/22/21

LOCATION/RM #: BLDG2 WO# 13155 ASSET # 10624  
13156 10625

START TIME: 3pm

FINISH TIME: 3:30pm

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
SPECIAL INSTRUCTIONS				
1	Schedule shutdown with operating personnel.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
2	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check valve for signs of abnormal wear and leaks. Replace packing if needed.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	no wear or leaks found
2	Clean the coils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	coils are clean
3	Comb the fins as needed.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	fins are good
4	Clean all fans and motors.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	fans and motors are clean
5	Check operation of controls and safeties.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	controls function properly
6	Lubricate as required.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	sealed motors
7	Check all motors, belts, pulleys, shafts, etc. for alignment.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	direct drive and motors are good

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.

To be performed by: General Maintenance Worker

**Additional Notes:**