

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039 Date of Visit: 6/25/21

Contractor Personnel on Site:

1. PATRICK BROWN 3. _____
2. _____ 4. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO#'S, 13061 , 13062 , 13262-13268 , 12881 ,
2. 13029 , 13030 , 13272 , 13282 , 13289 , 13303 ,
3. 13096 , 13304 , 13305 ,
4. ASSET#'S, 9891 , 9896 , 9932 , 9935 , 9893-9897 ,
5. 9931 , 9943 , 9939 , 190917-, 248 , 245 , 269 , 264 ,
267 , 270 , 274 , 275

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 6/25/21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SSGT maniewski Date: 6/25/21

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
FENCES

MECHANIC
 SIGNATURE: 

DATE: 6/25/21

SITE AND BLDG #: NY039 BLDG1

LOCATION/RM #: OUTSIDE

WO# 13272 ASSET #190917-245

START TIME: 11:30am

FINISH TIME: 12pm

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check posts and corner posts, support guys, and horizontal bars between each support post.	✓	/	all are good
2	Check wire and anchor point; re-stretch and re-anchor if necessary.	✓	/	
3	Inspect fence anchors along the bottom of the fence and at the point where the fence is connected to the post.	✓	/	fence anchors are good
4	Report any damage to fence that would cause a security concern	✓	/	no security concerns
5	Inspect the bottom of the fence to ensure that there is not a gap larger than 2 inches under the fence.	✓	/	no gaps
6	Check the top guard and ensure that it is properly fastened (angled out) and the wires are tight.	✓	/	top guard is properly fastened
7	Inspect all wire ties. Note any deficiencies	✓	/	no deficiencies found

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: