

Tina Lee

From: Richard Hicks
Sent: Tuesday, February 23, 2021 8:17 AM
To: Tina Lee
Subject: FW: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

Upload to WO# 13450

-----Original Message-----

From: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil>
Sent: Monday, February 8, 2021 10:56 AM
To: Richard Hicks <richard.hicks@cmimgmt.com>; Williams-Taylor, Angela W CTR USARMY 99 RD (USA) <angela.w.williams-taylor.ctr@mail.mil>
Cc: Tina Lee <Tina.Lee@cmimgmt.com>
Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

CLASSIFICATION: UNCLASSIFIED

Ok
Got it.

//////

Angela, do you want a ticket for the
PM - 13450--The LED light pole hand access covers need repaired-----I need a CSS# from you IF you would like
these covers repaired ?

Very Respectfully,

Scott A. Grenier
Regional Facility Operations Specialist
99th Div (R) DPW
1741 E Belt Blvd
Richmond, VA 23224
Cell: 254.220.8083
Office: 910.598.8339
Email: scott.a.grenier.civ@mail.mil

-----Original Message-----

From: Richard Hicks [mailto:richard.hicks@cmimgmt.com]
Sent: Monday, February 8, 2021 10:30 AM
To: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil>
Cc: Williams-Taylor, Angela W CTR USARMY 99 RD (USA) <angela.w.williams-taylor.ctr@mail.mil>; Tina Lee <Tina.Lee@cmimgmt.com>

Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

Scott,

No both tickets are active and separate -WO#13134- One parking lot pole light out near motorcycle parking area, needs repaired,-MOORE'S has investigated and pulling a proposal together as we speak .---

Corrective Maintenance WO# 13450 -was the ticket I created and requested CSS# for last month -Richard discovered during his PM - 13450--The LED light pole hand access covers need repaired-----I need a CSS# from you IF you would like these covers repaired

Thanks

Rick

Rick Hicks
Project Manager Region 5
CMI Management Inc.
5285 Shawnee Road Suite #510
Alexandria,VA 22312
703-738-5301
Richard.Hicks@cmimgmt.com

-----Original Message-----

From: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil>
Sent: Monday, February 8, 2021 10:04 AM
To: Richard Hicks <richard.hicks@cmimgmt.com>
Cc: Williams-Taylor, Angela W CTR USARMY 99 RD (USA) <angela.w.williams-taylor.ctr@mail.mil>
Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

CLASSIFICATION: UNCLASSIFIED

Yes

So you closed WO#13134 and you want me to replace with 13450?

Angela, said she thought Richard was going to order parts to get fixed.

Very Respectfully,

Scott A. Grenier
Regional Facility Operations Specialist
99th Div (R) DPW
1741 E Belt Blvd
Richmond, VA 23224
Cell: 254.220.8083
Office: 910.598.8339
Email: scott.a.grenier.civ@mail.mil

-----Original Message-----

From: Richard Hicks [mailto:richard.hicks@cmimgmt.com]

Sent: Monday, February 8, 2021 9:27 AM

To: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil>

Subject: FW: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

All active links contained in this email were disabled. Please verify the identity of the sender, and confirm the authenticity of all links contained within the message prior to copying and pasting the address to a Web browser.

Hi Scott -Just a reminder .Do you want to open a ticket to get these covers repaired or is Angela getting it fixed under warranty ?

Thanks

Rick

Rick Hicks

Project Manager Region 5

CMI Management Inc.

5285 Shawnee Road Suite #510

Alexandria,VA 22312

703-738-5301

Richard.Hicks@cmimgmt.com

From: Richard Hicks
Sent: Monday, January 4, 2021 3:04 PM
To: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil> <Caution-mailto:scott.a.grenier.civ@mail.mil>
Subject: FW: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

Hi Scott

I dug into this today .

- * See all the strings below .
- * And Moore's email attached .
- * WO# 13134 Moore's didn't perform any service on the lights.
- * Richard discovered this performing January light PM , and that's why I created WO# 13450 pending CSS# .

- * Maximo notes : 12/21- Moore's onsite 12/18- no access -Angela said to leave --Moore's showed up 1.5 hours early
- * 1/4/2021 - Scheduling for 1/6/2021 at 9am

13134

[S Grenier]One parking lot pole light out near motorcycle parking area, needs repaired, upcoming safety

99REG5

VA701-01

3002-AW

27317

Z3

2

INPRG-C

SC

Thanks

Rick

Rick Hicks

Project Manager Region 5

CMI Management Inc.

5285 Shawnee Road Suite #510

Alexandria,VA 22312

703-738-5301

Richard.Hicks@cmimgmt.com < Caution-mailto:Richard.Hicks@cmimgmt.com >

From: Adam Colopy <adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net > >
Sent: Monday, January 4, 2021 2:39 PM
To: Mary Lowery <Mary.Lowery@tideh2o.net < Caution-mailto:Mary.Lowery@tideh2o.net > >; Richard Hicks <richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com > >
Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS#
IF you want these repaired . (UNCLASSIFIED)

Rick,

See attached. Moore's didn't perform any service on the lights.

Adam Colopy, FMP

Regional Operations Manager

TIDEWATER, INC.

adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net >

3761 Attucks Drive

Powell, OH 43065

C: 740-819-6207

From: Mary Lowery <Mary.Lowery@tideh2o.net < Caution-mailto:Mary.Lowery@tideh2o.net > >
Sent: Monday, January 4, 2021 11:46 AM
To: Adam Colopy <adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net > >; Richard Hicks <richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com > >
Subject: Re: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

Ok, on it right now.

Get Outlook for iOS < Caution-https://aka.ms/o0ukef >

From: Adam Colopy <adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net > >
Sent: Monday, January 4, 2021 11:45:21 AM
To: Richard Hicks <richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com > >
Cc: Mary Lowery <Mary.Lowery@tideh2o.net < Caution-mailto:Mary.Lowery@tideh2o.net > >
Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

Mary,

Please reach out to Moore's to find out if they did any work on these pole lights the day they went out there and ended up leaving because they couldn't get access (WO 13134). Did they take the covers off the poles or anything?

Adam Colopy, FMP

Regional Operations Manager

TIDEWATER, INC.

adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net >

3761 Attucks Drive

Powell, OH 43065

C: 740-819-6207

From: Adam Colopy

Sent: Monday, January 4, 2021 11:39 AM

To: Richard Hicks <richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com > >

Cc: Mary Lowery <Mary.Lowery@tideh2o.net < Caution-mailto:Mary.Lowery@tideh2o.net > >

Subject: FW: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

FYI

Adam Colopy, FMP

Regional Operations Manager

TIDEWATER, INC.

adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net >

3761 Attucks Drive

Powell, OH 43065

C: 740-819-6207

From: Richard Walker <richard.walker@tideh2o.net < Caution-mailto:richard.walker@tideh2o.net > >
Sent: Monday, January 4, 2021 11:36 AM
To: Adam Colopy <adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net > >
Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS#
IF you want these repaired . (UNCLASSIFIED)

All screws were present. However multiple brackets were missing. And the screws are plastic and some had broken internal inside the pole. Also, there was multiple pole handhole covers with rubber holding them on. And 2 hand hole covers laying on ground next to poles.

You couldn't tell the screws weren't holding the covers on by just looking at it.

It was only after attempting to unscrew them and it not working to loosen the covers.

Sent from my Sprint Tablet.

----- Original message -----

From: Adam Colopy <adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net > >

Date: 1/4/21 11:22 AM (GMT-05:00)

To: Richard Walker <richard.walker@tideh2o.net < Caution-mailto:richard.walker@tideh2o.net > >

Cc: Richard Hicks <richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com > >, Mary Lowery <Mary.Lowery@tideh2o.net < Caution-mailto:Mary.Lowery@tideh2o.net > >

Subject: FW: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS#
IF you want these repaired . (UNCLASSIFIED)

Richard,

See string below. Any idea on on this?

Adam Colopy, FMP
Regional Operations Manager
TIDEWATER, INC.

adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net >
3761 Attucks Drive
Powell, OH 43065

C: 740-819-6207

-----Original Message-----

From: Richard Hicks <richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com > >
Sent: Monday, January 4, 2021 11:18 AM
To: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil < Caution-mailto:scott.a.grenier.civ@mail.mil > >
Cc: Adam Colopy <adam.colopy@tideh2o.net < Caution-mailto:adam.colopy@tideh2o.net > >; Mary Lowery <Mary.Lowery@tideh2o.net < Caution-mailto:Mary.Lowery@tideh2o.net > >
Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

Adam ,
Please check with Richard on this .see string below

Rick

Rick Hicks
Project Manager Region 5
CMI Management Inc.
5285 Shawnee Road Suite #510
Alexandria,VA 22312
703-738-5301
Richard.Hicks@cmimgmt.com < Caution-mailto:Richard.Hicks@cmimgmt.com >

-----Original Message-----

From: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil < Caution-mailto:scott.a.grenier.civ@mail.mil > >
Sent: Monday, January 4, 2021 11:14 AM
To: Richard Hicks <richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com > >
Subject: RE: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired . (UNCLASSIFIED)

CLASSIFICATION: UNCLASSIFIED

Hi Rick
Angela had a question on this:
" Scott,

Moore's were on site looking at the pole lights on or about the third week of December, did they leave the screws loose? I don't recall any screws missing on my last visit. We have CSS #27317 in for light pole repair."

Very Respectfully,

Scott A. Grenier
Regional Facility Operations Specialist
99th Div (R) DPW
1741 E Belt Blvd
Richmond, VA 23224
Cell: 254.220.8083
Office: 910.598.8339
Email: scott.a.grenier.civ@mail.mil < Caution-mailto:scott.a.grenier.civ@mail.mil >

-----Original Message-----

From: Richard Hicks [Caution-mailto:richard.hicks@cmimgmt.com < Caution-mailto:richard.hicks@cmimgmt.com >]
Sent: Monday, January 4, 2021 8:02 AM
To: Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil < Caution-mailto:scott.a.grenier.civ@mail.mil > >
Cc: Devlin, Thomas J CIV USARMY CENAP (USA) <Thomas.J.Devlin@usace.army.mil < Caution-mailto:Thomas.J.Devlin@usace.army.mil > >
Subject: [Non-DoD Source] VA701 CM WO# 13450 CSS# Pending --I have created WO# 13450 -please provide a CSS# IF you want these repaired .

All active links contained in this email were disabled. Please verify the identity of the sender, and confirm the authenticity of all links contained within the message prior to copying and pasting the address to a Web browser.

Good Morning Scott,

VA701- Light pole hand access covers need repaired . I have created WO# 13450 -please provide a CSS# IF you want these repaired .

12/29/2020- -During PM -Richard found -

The LED light pole hand access covers need repaired

Found: 9 broken plastic screws and 3 missing brackets, In the LED light pole hand hole covers.

The hand hole covers had been attached with a sealant to bypass the bracket and screws

1/4/2020 -Will request CSS# from Scott

12/29/2020-CM credit will be applied

Thanks

Rick

Rick Hicks

Project Manager Region 5

CMI Management Inc.

5285 Shawnee Road Suite #510

Alexandria,VA 22312

703-738-5301

Richard.Hicks@cmimgmt.com < Caution-mailto:Richard.Hicks@cmimgmt.com > < Caution-Caution-mailto:Richard.Hicks@cmimgmt.com >

CLASSIFICATION: UNCLASSIFIED

CLASSIFICATION: UNCLASSIFIED

CLASSIFICATION: UNCLASSIFIED