

Date: 9/19/2023

Region: 4C
FAC ID: WV002

CSS No.: 89878
Maximo WO No.: 13384

Asset #:

Priority: 2



Original Work Request:

Watts Regulator 300 psi 2" pressure release valve is not holding pressure on the main water line, needs replacing

Description of Repairs Needed:

Replace 2" pressure reducing valve..This estimate may be subject to a change order pending the regulator not fitting without changing the existing water line. The technician will not know if this is required until he gets the part in hand.

Labor:

	Labor Hrs	Labor Rate	Total
2 Techs	8	\$158	\$ 1,263.76
Mobilization/Travel	1	\$ 229.00	\$ 229.00

Material List:

	Quantity	Cost	Total
Watts 2" Pressure Reducing Valve (2LFN55BU)	1	\$ 778.02	\$ 778.02
Miscellaneous	1	\$25.00	\$ 25.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,492.76	\$803.02	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,295.78	\$275.49	\$137.75	\$2,709.02