

Date: 11-08-23

Region: 4C

FAC ID: WV002

CSS No.: 89880

Maximo WO No.: 14264

Asset #:

Priority:



Original Work Request:

Replace 3 HW valve actuators for the VAV boxes that have gone bad.

Description of Repairs Needed:

Investigate and replace six (6) air flow pressure transducers and three (3) HW valve actuators for VAV boxes.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1) Investigate Repair	2.5	\$ 132.00	\$ 330.00
Tech (1) Repair	8	\$ 132.00	\$ 1,056.00

Material List:	Quantity	Cost	Total
Trip Charge - Investigate Repair	20	\$ 1.75	\$ 35.00
Trip Charge- Repair	20	\$ 1.75	\$ 35.00
Trane Transducer - (Tdr00754)	6	\$ 339.72	\$ 2,038.32
Trane Actuator - (act00374)	3	\$ 203.01	\$ 609.03
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$1,386.00	\$2,717.35	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,103.35	\$492.40	\$246.20	\$4,841.95