

Date: 1-30-24

Region: 4C

FAC ID: WV006

CSS No.: 96618

Maximo WO No.: 15002

Asset #:

Priority:



Original Work Request:

The carpet in the Conference Room of the Training Facility was damaged by mold and was removed. We need to recarpet the room with new carpet squares. Recommended contractor: Nitro Carpet Outlet (304) 769-0495.

Description of Repairs Needed:

Replaced damaged carpet with new carpet squares.

Labor:	Labor Hrs	Labor Rate	Total
Tech	1	\$ 1,922.00	\$ 1,922.00
			\$ -

Material List:	Quantity	Cost	Total
18 Ctns (144 SY) Pentz Uplink Color Charcoal 24x24 tiles	18	\$ 111.92	\$ 2,014.56
Adhesive (2 pails)	2	\$ 175.00	\$ 350.00
Rubber Tmold	1	\$ 30.00	\$ 30.00
Rubber Reducer	1	\$ 30.00	\$ 30.00
Freight	1	\$ 225.00	\$ 225.00
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,922.00	\$2,649.56	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,571.56	\$548.59	\$274.29	\$5,394.44