

**PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST**  
**DOMESTIC HOT WATER HEATER - ELECTRIC**

SITE AND BLDG #: WV020-01

LOCATION/RM #: BoILER ROOM

MECHANIC  
SIGNATURE:

Geo. E. J.  
DATE: 12AUG19

START TIME: 12:45

FINISH TIME: 1:45

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
WV020-01	10428	7046			NR-240-NG	8880-20100426-3017	J-1502000-27 1-pc Water Heater Rm 111	
WV020-01	10428	7047			NR-240-NG	194IB009	J-1502000-27 1-pc Water Heater Rm 111	
WV020-01	10428	7048			NR-240-NG		J-1502000-27 1-pc Water Heater Rm 111	
WV020-01	10428	7049			NR-240-NG	202JB005	J-1502000-27 1-pc Water Heater Rm 111	

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
<b>SPECIAL INSTRUCTIONS</b>				
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.	✓		
2	Follow lock out/tag out procedures always. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	✓		
<b>TO BE PERFORMED AT EACH INSPECTION SERVICE</b>				
1	Attach drain hose. Drain several gallons from tank to remove sediment.		✓	<u>N/A ON DEMAND TANKLESS</u>
2	Manually check operation of safety valve. Check for corrosion around valve. Verify the safety valve inspection tag is in place. Ensure that no personnel are in area of relief piping discharge.	✓		
3	Check all connections - electric and water. Tighten as necessary. Ensure power is disconnected to electric heaters prior to checking connections.	✓		

4	Check operation/ setting of aqua stat. Check hot water temperature with dial thermometer, set aqua stat at minimum value required for all uses.	✓		125° 140°
5	Check amperage draw of upper and lower elements and compare to name plate data.		✓	N/A GAS FIRED
6	Clean element contacts and check for proper closing under load.	✓		✓
7	Clean pump, controls, switches, and starters. Check condition of pump seal or packing and replace as required.	✓		
8	If applicable, Remove and inspect Anode, replace if necessary		✓	N/A
9	Clean up work area and remove trash.	✓		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker Additional Notes:

MASTER UNIT ASSET# 7046 INOP, LEAKING AT  
FLEAT EXCHANGER- QUOTE HAS BEEN PROVIDED BY CASTOTECH  
FOR REPAIRS

