

Date: 9-11-24

Region: 4C

FAC ID: WV024

CSS No.: 98259

Maximo WO No.: 16392

Asset #:

Priority: 2



Original Work Request:

Asset 4136 and 4137 both have bad fan motors that need replacing. Discovered during PMs by CMI

Description of Repairs Needed:

Proposal is to replace two fan motors identified during PMs as not working.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -

Material List:

	Quantity	Cost	Total
Trane - MOTO7939 (1/3 HP, 120V, 1.8A)	2	\$ 240.00	\$ 480.00
freight	1	\$ 35.00	\$ 35.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$515.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$915.00	\$109.80	\$54.90	\$1,079.70