

Date: 4-5-24

Region: 4C

FAC ID: WV035

CSS No.: 97476

Maximo WO No.: 15426

Asset #:

Priority: 1



Original Work Request:

CMI has requested per COR (Luke) that an additional CSS ticket be submitted for Casto to provide a quote to replace the electrodes in the segmented boiler.

Description of Repairs Needed:

Investment is to replace the electrode igniter for the oil burner on Burnham Boiler (M# V9A/V11; S# 123445)

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	6	\$ 132.00	\$ 792.00
Trip Charge	60	\$ 1.75	\$ 105.00

Material List:	Quantity	Cost	Total
X04241 Powerflame (L) Electrode	4	\$ 17.10	\$ 68.40
X04242 Powerflame ® Electrode	4	\$ 15.20	\$ 60.80
NDA Shipping & Handling	1	\$ 162.50	\$ 162.50
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$897.00	\$291.70	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,188.70	\$142.64	\$71.32	\$1,402.67