

Date: 4-13-26



Region: 4C

FEMS/CSS No.: 2966470

FAC ID: WV035

Maximo WO No.: 21689

Asset #:

Priority: 2

Original Work Request:

It is recommended for all 4 PTACs be replaced despite some of them currently running. The delay was to see the outcome of the replacement of the ones in the shop. They are all a ticking time bomb for pin hole water leaks in carpeted offices like what happened in the OMS shop. The PtACs were investigated by Casto and the report was forwarded

Description of Repairs Needed:

Proposal is for the IDIQ increase amount due to the original quote being no longer valid due to length of time to approve the quote.

Labor:

	Labor Hrs	Labor Rate	Total
Labor	40	\$ 7.00	\$ 280.00
Troubleshooting Overtime	2	\$ 10.50	\$ 21.00
			\$ -

Material List:

	Quantity	Cost	Total
PTC 123J00HXXX PTAC	4	\$ 51.67	\$ 206.66
VW2SNOA-2 way water valve	4	\$ 19.66	\$ 78.62
WS916D-CFA 16" Wall Sleeve	4	\$ 20.03	\$ 80.13
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$301.00	\$365.41	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$666.41	\$79.97	\$39.98	\$786.36