

Date: 1-28-25

Region: 4C

FAC ID: WV035

FEMS/CSS No.: 2992446

Maximo WO No.:

Asset #:

Priority: 2



Original Work Request:

CMI requested a FEMS ticket for replacing 2 Exhaust fan motors

Description of Repairs Needed:

Proposal is to replace motor on one exhaust fan and replace entire exhaust fan on second unit.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 100.00	\$ 800.00
			\$ -
			\$ -

Material List:	Quantity	Cost	Total
Motor - A.O. Smith GF2024, 115V, 1/4Hp, 1725 rpm	1	\$ 266.50	\$ 266.50
Downblast Roof Axial Air (FICBXRA) 1/6 HP, 115V, PH1; size			\$ -
RMUA14, 1160 CFM	1	\$ 475.00	\$ 475.00
Shipping	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$800.00	\$791.50	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,591.50	\$190.98	\$95.49	\$1,877.97