

Date: 1-21-26

Region: 4C

FAC ID: WV035

FEMS/CSS No.: 3432865

Maximo WO No.: 21188

Asset #:

Priority: 2



**Original Work Request:**

PTAC in front office of OMS Shop making noise similar to PTAC in the right office that CMI just fixed. It's fan needed replacing

**Description of Repairs Needed:**

Labor to troubleshoot, diagnose and make necessary repairs and adjustments to the OMS front office PTAC. Discovered pieces of heat shielding had fallen into condenser fan causing noise.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 131.00	\$ 524.00
Trip Charge	1	\$ 131.25	\$ 131.25
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$655.25	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$655.25	\$78.63	\$39.32	\$773.20