

CMI Management
 VA-011
 1821 Industry St.
 Culpeper VA 22701
 (202) 437-5119

Recorded By: Marshall Kohne
 (301) 721-2663
 mkohne@bondwater.com

Culpeper Minutemen Mem USARC - HVAC Equipment

Test	Evap Condenser			
Conductivity (as mmhos)	932 900 - 1350			
pH	8.3 7 - 9			
Chlorides	30 80 - 180			
Hardness, total (ppm as CaCO ₃)	350 750 max			
Alkalinity, total (ppm as CaCO ₃)	80 400 max			
Molybdate (ppm as Mo)	1.2 0.8 - 1.2			

Evaporative Condenser

Online 

All readings were found within desired ranges except for chlorides being low due to cold weather and system inactivity, nothing to be concerned with. Inspected overall operating condition of water treatment equipment and determined everything is working properly. Filled necessary feed tanks and ensured all chemical pumps are primed.

Closed Loop

Online 

Mechanical contractor on site installing new boiler. I will return on 11/29 and will chemically treat the new system as needed.

Bond Water Technologies, Inc. recommends that you perform regular and/or daily analysis to control chemical levels and cycles of concentration within established limits. Test results reflect conditions during the point in time when the analysis was performed. Additional testing may be performed upon request. As operating conditions vary, test results will change over time. Notwithstanding anything to the contrary contained in the Agreement or otherwise, (i) Bond Water Technologies and its insurers are not liable for losses caused by the Customer's wrongful acts or omissions, (ii) Bond's program does not cover and it makes no guarantees with respect to waterborne pathogens including Legionella or against health risks therefrom, and (iii) in no event shall either party be liable for any consequential or indirect damages.