

**PROJECT ESTIMATE**

DATE: 06/10/2019

QUOTE ID:	3851	CONTACT:	RON VOGT - CELL
AR CUSTOMER:	CMI MANAGEMENT (#10343)		Ph:(315) 772-8801
SERVICE LOCATION:	US ARMY RESERVE - PL		Fax:(315) 772-6336
STREET:	5363 PERU STREET, ROUTE 9	DATE	steve.miller@cmimgmt.com
CITY:	PLATTSBURGH, NY 12901	SUBMITTED:	06/10/2019
		PREPARED BY:	FRASHER, LINDA

DESCRIPTION: Repair Leak in Small Fan Coil in Gym

SCOPE OF WORK: WO# 4099 CSS19293/NY054

We were asked to check a leak. Our technician made the following notes:

Need lift to make repairs - found small fan coil in gym room leaking from union. Recommend replacing two 1.25 unions and two 1.25x 3-6 nipples.

The pricing shown below covers labor and materials required to do this work. The diagnostic call is being invoiced separately. Please call me at extension #236 if you have any questions. Thank you.

ITEM	QUANTITY	UNIT PRICE	TOTAL
Labor Regular Time	6	\$110.00	\$660.00
Nipples, Unions and Misc.	1	\$24.00	\$24.00
Environmental Fee	1	\$12.00	\$12.00
Lift	1	\$207.36	\$207.36
Total			\$903.36

SIGNATURE

PRINT NAME

DATE



PROJECT ESTIMATE

DATE: 06/10/2019

All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from the above specifications involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. Our technicians are covered by New York State Workers Compensation Insurance.

QUOTE VALID FOR THIRTY (30) DAYS

Credit Card Payments over \$5,000.00 will be charged an additional 3% fee