

LIGHTING, OUTSIDE

SITE AND BLDG #: PY024-358

**MECHANIC
SIGNATURE**

DATE:

LOCATION/RM #:

#OM

ASSET #

START TIME:

FINISH TIME:

No.	Description	Date	Time	Signature	Remarks
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.				
2	Schedule and coordinate work with operating personnel.				
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.				
4	Open and tag switch.				
5	Inspect visual condition of wiring. Look for evidence of overheating.				
6	Check for proper light operation.				
7	Test operation of automatic switches/ time clock/ photocells if applicable.				
8	Inspect light pole and mounting devices for deficiencies.				
9	For any noted deficiency, takes pictures and open corrective maintenance ticket.				

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.
To be performed by: General Maintenance Worker

Additional Notes:

A5589 - W-2 #
PK-40-9807 - 6208 - Don't work
PK-5A-9806-6407 They aware of it.