

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST ICE MAKER

SITE AND BLDG #: NY060 - 01 **Main Building**

LOCATION/RM #: Kitchen WO# 5829 ASSET # 10456

MECHANIC

SIGNATURE: Christopher N Pothier DATE: 11 - 14 - 19

START TIME:

FINISH TIME:

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
SPECIAL INSTRUCTIONS				
1	Review manufacturer's instructions.	X		
2	De-energize, lock out, and tag electrical circuits.	X		
3	If appliance is disposed, follow regulations concerning removal of refrigerants and disposal of the appliance.	X		
4	If materials containing refrigerants are discarded, comply with EPA regulations as applicable.	X		
5	Only approved cleaning chemicals shall be used.	X		
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check with operating or area personnel for any deficiencies; verify cleaning program.	X		
2	Visually check for refrigerant, oil and water leaks.	X		
3	Inspect ice condition/size.	X		
4	As needed, drain and clean unit with proper ice machine cleaning solution.	X		
5	Check date on water filter, Replace as needed. Water filters should be changed annually at a minimum.		X	Unit does not have a filter
6	Check and tighten any loose screw-type electrical connections.	X		
7	Check all controls; adjust if necessary.	X		
8	Examine water connection; open and close water valve; test ice dispensing valve and (door) metering adjustment.		X	See Notes
9	Check and clear ice machine draining system (drain vent, strainer, trap).	X		
10	Examine condition of bin doors-closure, hinges, gaskets, handles and ease of slide; lubricate as required. Check storage bin condition.	X		
11	Clean motor, compressor, and condenser coil.	X		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: This unit had an error when I first got to it. At first ice would not drop from the evap coil and just continued to freeze into one large block. After some adjustments it would dispense but the bin sensor says the bin is full no matter what I do.