

SITE AND BLDG #:	WO#	ASSET #
22740-01		

START TIME:

DATE: / /

1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.	☒		AGSEA # 107552
2	Schedule and coordinate work with operating personnel.	☒		8 PCSOAR POWER
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	☒		DABBL - 6 LIC445, OUR THEY AWARE OF IT
1	Open and tag switch.	☒		
2	Inspect visual condition of wiring. Look for evidence of overheating.	☒		
3	Check for proper light operation.	☒		
4	Test operation of automatic switches/ time clock/ photocells if applicable.	☒		CLARK IN EAPC
5	Inspect light pole and mounting devices for deficiencies.	☒		
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.	☒		

Additional Notes:

ASST #

2. 04