

Additional Funding Request

DE007	CSS# 31505 WO# 14544				
Description of Repairs	Labor and materials to replace 4 domestic water system temperature gauges in mechanical room.				
Diagnosis: Initial Work Order	Hot water heater temperature gauges bad and need to be replaced				
Diagnostic Fee	\$ 160 Labor \$80/hr x 2				
Additional Labor Cost to Perform Repairs	\$ 400 Labor \$80/hr x 5				
Additional Material Cost to Perform Repairs	\$ 505.28 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 45%;">Industrial Glass Thermometer</td> <td style="width: 10%;">4</td> <td style="width: 15%;">126.32</td> <td style="width: 30%;">505.28</td> </tr> </table>	Industrial Glass Thermometer	4	126.32	505.28
Industrial Glass Thermometer	4	126.32	505.28		
Total Cost of Repair	\$ 1065.28				



WORK ESTIMATE

CSS #: 31505

Work Order #: 14544

Emergency

Urgent

Routine X

Company Name:	Tidewater, Inc.		Facility ID:	DE007
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	John Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials replace 4 domestic water system temperature gauges in Mechcanical room .

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagostic			2	\$160.00
Industrial Glass Thermometer	4	\$126.32		\$505.28
Labor			5	\$400.00
SUB-TOTAL COSTS:	Materials Total	\$505.28	Labor	\$560.00
			TOTAL	\$1,065.28

My Products Reference Information

WINTERS



Item # 20187
Location, 6 in Stem Length
Vari-Angle Connection
Industrial Glass Thermometer,

Item # 20187

4
5100.25 / each

Total \$401.00

Reference Information

Name

Cart

Order

Ware

0

